

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|---|------|----------------|
| CAMPAIGN No. | 5135 | DATE | April 26, 2022 |
| MANUFACTURER | NIPPON FRUEHAUF COMPANY LIMITED | | |
| DESCRIPTION OF DEFECT | Some semi-trailer braking systems are equipped with brake chambers that do not allow disassembly of the service brake chamber. As a result, periodic replacement parts inside the service brake chamber, as specified in the inspection and maintenance system, cannot be replaced. | | |

| MANUFACTURER'S NAME | TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------------------|-----------|------------------------|---------------------|-------------------|
| FRUEHAUF | KFKGF340W | Container Semi Trailer | 2020 | 1 |
| | KFPDX339A | Container Semi Trailer | 2021 | 1 |
| | | | Total | 2 |