

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	外-3396	DATE	April 26, 2022
MANUFACTURER	AGCO S. A. S. (Japanese Importer: ISEKI & CO., LTD.)		
DESCRIPTION OF DEFECT	In the braking devices of agricultural tractor, air is mixed into the hydraulic circuit due to inadequate design of the hydraulic circuit. Therefore, if the vehicle is used as it is, the braking performance may deteriorate. We will add a check valve to the brake hydraulic circuit of all vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-T243F	T7726-V	2016~2018	9
	T7726S-V	2018~2021	14
YDS-T244F	T7722-V	2016~2018	6
	T7722S-V	2018~2020	9
YDS-T245F	T7719-V	2016~2018	12
	T7719S-V	2018~2021	8
YDS-T246F	T7718-V	2016~2018	13
	T7718S-V	2018~2021	17
YDS-T247F	T7716-V	2016~2018	11
	T7716S-V	2019	1
YDR-T248F	T7715-V	2016~2018	10
	T7715S-V	2019~2021	6
YDS-T266F	T6716S-V	2018~2019	2
YDR-T268F	T6714S-V	2018~2021	4
		TOTAL	122