## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5136	DATE	Apr. 21, 2022		
MANUFACTURER	SUZUKI MOTOR CORPORATION				
DESCRIPTION OF DEFECT	Incorrect roof antenna, that has the different shape from the original, was installed in the vehicle, due to the improper work instruction.  The vehicle height value may become different from that stated in the vehicle approval, as the result of the above miss-build.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
4AA-MN71S	XBEE	2022	14
		TOTAL	14