

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5138	DATE	Apr.21 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	For some heavy-duty tractors, the brake lamp circuit on the trailer side is inappropriate, so that diode in the circuit may burn out while the brake lamps are turned on. As a result, the brake lamps on the trailer may become inoperable and a brake lamp failure warning may be displayed. In the worst case, a fire will occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HJR	「FUSO SUPER GREAT」	2017~2021	656
2KG-FV74HJR		2018~2021	72
2KG-FV70HYP		2019~2021	86
2KG-FV70HZP		2019~2021	25
2PG-FV74HJR		2018~2021	65
2PG-FP74GGR		2018~2021	31
2RG-FP74HDR		2017~2021	2,463
2RG-FP74HER		2017~2021	1,069
2RG-FP74HGR		2017~2021	158
			TOTAL