

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3391	Date	April 21, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	The engine compartment cover on the power unit can become detached from its retainers depending on service life and vehicle use (very sporty driving style or poor road surfaces). If the engine compartment cover is not securely attached, it can potentially come into contact with the hot area of the turbocharger, leading to smoldering damage or even a fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-CDDNP	Golf GTI 2.0/180kW	MY2022	264
3BA-5NDNFF	Tiguan R 2.0/235kW	MY2021-MY2022	192
		Total	456