

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3390	DATE	April 18 <sup>th</sup> , 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate OBD software which have been implemented at dealership, certain input parameters (sensor signals) could be misinterpreted, which could lead to torque reduction and possibly to the engine failure while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-JC20	「BMW 523d」	2016～2019	141
	「BMW 523d Touring」	2017	5
LDA-JM20		2017～2019	46
LDA-TX20	「BMW X3 xDrive 20d」	2017～2019	414
		TOTAL	606