## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic / Import Vehicles

CAMPAIGN No.		DATE	06.04, 2022	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer: SCAN	IA JAPANA Co. Ltd.		
DESCRIPTION OF DEFECT	In some air pressure control systems (APS), the airtightness of the air pressure cannot be maintained due to improper design of the air dryer regeneration control valve. Therefore, there is a risk that air leakage will occur, the warning light will light up, or the air pressure will not rise after the engine is started, and the parking brake will not be released, making it impossible to drive.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	SCANIA (8x4)	<mark>2021</mark>	1
		TOTAL	1