

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3357	DATE	4th Apr. 2022
MANUFACTURE	MUTT MOTORCYCLES LTD. (Japanese Importer : PCI.co.Ltd)		
DESCRIPTION OF DEFECT	Rear brake caliper bracket does not properly welded to swingarm due to incorrect data entry to a welder machine. The bracket may break by strong force and rear brake caliper may not be fixed to the body.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HA7KJB4B	MUTT 125 SABBATH	2021	13
	MUTT 125 HILTS	2021	8
	MUTT 125 MONGREL	2021	4
	MUTT 125 AKITA	2021	2
	MUTT 125 FSR	2021	2
	MUTT 125 RS-13	2021	1
	TOTAL		30