

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3386	DATE	April 1, 2022
MANUFACTURER	ALPINA Bruckard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing of characteristic map thermostat, possible burr residue may cause the coolant entering the plug connection. In this case, the engine control unit may detect malfunction, and this then results in a CC message (MIL on).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-7M50	B7 Long AWD	2021	1
		TOTAL	1