

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

| | | | |
|-----------------------|---|------|----------|
| CAMPAIGN No. | Gai-3389 | DATE | 2022/4/1 |
| MANUFACTURE | Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | On certain S-Class (223 platform) vehicles, the welding of the console for the thrust arm on the rear axle carrier might not meet specifications. In this case, the welding could suddenly and without advanced warning fail so that the thrust arm would detach from the rear axle carrier. As a result, the vehicle might rock due to road excitation. In addition, the vehicle could pull away aside in the event of an emergency braking. Should this be the case, the controllability of the vehicle would be impaired, increasing the risk of a crash. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|------------------------------|---------------------|-------------------|
| 3DA-223033 | S400d 4MATIC | 2022 | 2 |
| 5AA-223063 | S500 4MATIC | | 6 |
| 4AA-223076 | S580 4MATIC | | 6 |
| 4AA-223176 | | | 4 |
| 7AA-223976 | Mercedes-Maybach S580 4MATIC | | 1 |
| | | TOTAL | 19 |