

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 1 4 9	DATE	May23.2022
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the braking device of a rotary snowplow, Since the shape of the mounting part of the pulley for the air compressor is improper, the nut for fixing the pulley may loosen due to vibration during running, and the pulley may fall off. Therefore, if the vehicle is used as it is, air will not be accumulated, and in the worst case, the brake may not work.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
R 0 2 C	H T R 2 6 8 L	2 0 1 9 ~ 2 0 2 1 R02C-0001 ~ R02C-0006	6
			TOTAL
			6

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where