

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 1 5 0	DATE	May23. 2022
MANUFACTURER	NICHIJO CORPORATION		
DESCRIPTION OF DEFECT	Control device of rotary snowplow, Since the strength of the forward / reverse shifting lever is inappropriate, if you continue to use it as it is, the contact part will wear, and in the worst case, the forward / backward shifting lever will break. There is a risk that forward / backward operation will not be possible.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-R03E	HTR308	2016~2018 R03E-0002~ R03E-0114	101
YDS-R03F	HTR308A	2018~2022 R03F-0002~ R03F-0266	229
YDS-R06E	HTR408	2016~2022 R06E-0002~ R006E-0056	51
YDS-R01E	HTR608	2015~2021 R01E-0001~ R01E-0019、R01E-1001	14
R02C	HTR268L	2019~2022 R02C-0001~R02C-0007	7
R06F	HTR410	2021 R06F-0001~ R16F-0003	3
TOTAL			405

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where