

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3394	DATE	May 10, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	The gateway control unit may be damaged by moisture entering under the rear seat bench. This may be caused by liquids spilt in the area of the rear seat bench and/or by a seal which may not have been made correctly on the vehicle underbody when driving through heavy rain or deep water. Damage to the gateway control unit may have effects on various vehicle functions. Restricted functions relating to this are indicated by warning messages in the instrument cluster.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-FYDGKA	Audi Q5 45Tq Air-suspension	2021	18
3AA-FYDGKS	Audi Q5 45Tq	2021	60
3BA-FYCWGA	Audi SQ5 Air-suspension	2021-2022	62
3BA-FYCWGS	Audi SQ5	2021-2022	74
3CA-FYDTPA	Audi Q5 40TDIq Air-suspension	2021-2022	81
3CA-FYDTPS	Audi Q5 40TDIq	2021-2022	1,970
ABA-FYCWGA	Audi SQ5 Air-suspension	2019-2020	187
ABA-FYCWGS	Audi SQ5	2018-2020	665
DBA-FYDAXA	Audi Q5 45Tq Air-suspension	2018-2020	616
DBA-FYDAXS	Audi Q5 45Tq	2017-2020	2,887
LDA-FYDETA	Audi Q5 40TDIq Air-suspension	2019-2020	524
LDA-FYDETS	Audi Q5 40TDIq	2019-2020	3,725
		Total	10,869