

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles )

CAMPAIGN No.	Gai-3438	DATE	2022/6/30
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain S-Class (BR 223) vehicles, the software of the rear signal acquisition and actuation module might not meet specifications.</p> <p>In this case, an incorrect initialization of the rear signal acquisition and actuation module might occur at start of the vehicle, resulting in a restriction of intended functions of the control unit. Among others, this condition might lead to a malfunction of the rear turn signal, rear hazard warning lights as well as the reversing light. This would be indicated to the driver in the instrument cluster by corresponding warning messages.</p> <p>The risk of a crash or injury might be increased. In addition, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-223033	S400d 4MATIC	2021	821
3DA-223133		2021	228
5AA-223063	S500 4MATIC	2021	1,614
5AA-223163		2021	1,623
		TOTAL	4,286