

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3441	DATE	2022/6/30
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On GLB (247 platform) vehicles, the level sensor linkage on the rear axle might not have been installed correctly. In this case, the levelling of the headlamp system could calibrate in the opposite direction if the rear seat, trunk or third row of seats were loaded appropriately. Subsequently, a blinding of the oncoming traffic cannot be ruled out, which would increase the risk of a crash. Furthermore, legal requirements might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-247684M	GLB180	2021	7
3DA-247613M	GLB200d 4MATIC		150
		TOTAL	157