

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3433	DATE	June 29, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	There may be a deviation in the tightening process of the fuel rail. As a result several bolts can come loose over the operating period, which can result in a message regarding a malfunction of the engine management system in the instrument cluster and to fuel smell due to the leak of fuel. In the worst case, there is a risk of vehicle cannot be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8UCZD	Audi Q3 1.4T	2015-2018	2,660
ABA-GACZE	Audi Q2 1.4T cod	2017-2018	879
DBA-8VCXS	Audi A3SB 1.4T 90kw	2015-2018	10,464
DBA-8VCXSL	Audi A3SEDAN 90kw	2015-2018	5,747
DBA-8XCZE	Audi A1 1.4T cod	2016-2018	262
		Total	20,012