

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3434	Date	June 29, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	There may be a deviation in the tightening process of the fuel rail. As a result several bolts can come loose over the operating period, which can result in a message regarding a malfunction of the engine management system in the instrument cluster and to fuel smell due to the leak of fuel. In the worst case, there is a risk of vehicle cannot be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-6RCJZ	VW Polo 1.2/66kW	MY2015-MY2017	20,187
DBA-6RCJZW	VW CrossPolo 1.2/66kW	MY2015-MY2017	651
DBA-6RCZE	VW Polo Blue GT/110kW	MY2016-MY2017	602
ABA-16CZD	The Beetle 1.4/110kW	MY2017-MY2019	1,051
ABA-16CZDW	The Beetle DUNE 1.4/110kW	MY2016-MY2017	794
ABA-AUCHP	Golf Variant 1.4/103kW	MY2017-MY2018	3,210
DBA-AUCHP	VW Golf Variant 1.4/103kW	MY2016-MY2017	2,238
DBA-AUCJZ	VW Golf 1.2/77kW	MY2015-MY2018	13,924
	VW Golf Variant 1.2/77kW	MY2015-MY2018	5,545
DBA-AUCPT	VW Golf 1.4/103kW	MY2015-MY2018	11,606
DBA-1TCZD	Golf Touran 1.4/110kW	MY2016-MY2019	11,341
ABA-5NCZE	Tiguan 1.4/110kW	MY2017-MY2018	5,829
DBA-3CCZE	Passat Sedan 1.4/110 k W	MY2015-MY2018	3,306
	Passat Variant 1.4/110 k W	MY2015-MY2019	7,226
DBA-7NCZD	Sharan 1.4/110 k W	MY2016-MY2019	3,731
Total			91,241