

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3435	Date	June 29, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the mechatronics of 7 speed DSG automatic transmission, due to the Inappropriate threading of the upper housing, some are lacking in durability. As a result, due to continuous accumulation of hydraulic pressure change, the upper housing may be cracked, and in the worst case, the driving force cannot be transmitted and the vehicle cannot be driven, because of insufficient hydraulic pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-1KCAX	VW Golf 1.4/90kW	MY2008-MY2009	2
	VW Golf Variant 1.4/90kW	MY2008	1
DBA-1KCAV	VW Golf Variant 1.4/118kW	MY2011-MY2012	11
DBA-1KCAX	VW Golf 1.4/90kW	MY2010-MY2013	27
	VW Golf Variant 1.4/90kW	MY2010-MY2012	16
DBA-1KCBZ	VW Golf 1.2/77kW	MY2010-MY2013	42
	VW Golf Variant 1.2/77kW	MY2013	5
DBA-AUCHP	VW Golf Variant 1.4/103kW	MY2015	80
DBA-AUCJZ	VW Golf 1.2/77kW	MY2015	920
	VW Golf Variant 1.2/77kW	MY2015-MY2016	100
DBA-AUCPT	VW Golf 1.4/103kW	MY2015	875
ABA-6RCGG	VW Polo 1.4/63kW	MY2010	1

ABA-6RDAJ	VW Polo GTI 1.8/141kW	MY2015-MY2016	238
DBA-6RCBZ	VW Polo 1.2/77kW	MY2011-MY2012	6
DBA-6RCJZ	VW Polo 1.2/66kW	MY2015	2,298
DBA-6RCJZW	VW CrossPolo 1.2/66kW	MY2015	204
DBA-6RCZE	VW Polo Blue GT/110kW	MY2015	305
DBA-16CBZ	VW The Beetle 1.2/77kW	MY2012-MY2015	947
DBA-16CBZK	VW The Beetle Cabriolet 1.2	MY2015-MY2016	60
DBA-1TCTH	VW Touran 1.4/103kW	MY2013-MY2015	226
DBA-1TCTHW	VW Cross Touran 1.4/103kW	MY2013-MY2015	35
DBA-3CCAX	VW Passat Variant 1.4T	MY2012-MY2013	12
DBA-3CCZE	Passat Variant 1.4/110kW	MY2015	1
ABA-3CCDAC	VW CC 1.8T	MY2013-MY2015	10
		Total	6,422