

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3436	DATE	29 th June 2022
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The rear brake disc and ABS pulser ring are retained by 4 bolts. It may be possible for one or more bolts to loosen. The loosed ABS pulser ring will be caouse of ABS system error and ABS function will be disabled.		

2BL-PSJ1200	Speed Triple RS	2022	228
8BL-PSJ1200	Speed Triple RR		66
		TOTAL	294