

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3410	DATE	27 June, 2022
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the protective fabric hose for the front seat wire harness on the affected vehicles will be damaged longitudinally when adjusting the seat and can then be pulled into the drive spindle for seat adjustment. This can block the seat adjustment, damage the wiring harness and activate the airbag warning light in the instrument cluster. In rare cases, the occupant protection system may be impaired.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1MB	Taycan 4S	2021	273
ZAA-J1MC	Taycan Turbo		79
ZAA-J1MD	Taycan Turbo S		99
ZAA-J1NA1	Taycan		4
ZAA-J1NA1C	Taycan		17
			Total