## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic / Import Vehicles

| CAMPAIGN No.          | Gai-3430  | DATE | Jun 27, 2022 |
|-----------------------|---|------|--------------|
| MANUFACTURE           | Royal Enfield (A unit of Eicl<br>(Japanese Importer : P   | •    |              |
| DESCRIPTION OF DEFECT | Brake calipers may be corroded by salt for melting snow. The corrosion of the brake calipers can cause the brakes to drag or braking performance could be affected or become ineffective. |      |              |

| TYPE    | COMMERCIAL<br>NAME | MODEL YEAR<br>RECALLED | NUMBER OF<br>VEHICLE |
|---------|--------------------|------------------------|----------------------|
| DME     | 「HIMALAYAN」        | 2019                   | 44                   |
| ME3EFLS | 「HIMALAYAN」        | 2020                   | 66                   |
|         | TOTAL              |                        | 110                  |