

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 3423	DATE	Jun. 13, 2021
MANUFACTURE	SCANIA CV AB (Japanese Importer: JALUX Inc.)		
DESCRIPTION OF DEFECT	Some cab auxiliary heater wiring is improperly positioned, Therefore the results in a significant chafing risk, with the heater control cable harness against the heater bracket. Therefore, there is a risk that malfunction of the heater or short circuit and Engine is not possible to turn off with key.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	Aerial platform vehicle	2020	2
		TOTAL	2