

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3426	DATE	June 13 th , 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Irregularities in the manufacturing process of the PCV valve and possible irregularities in the positive temperature coefficient insulation can cause a short circuit. As a result, thermal overload of surrounding plastic parts may occur, and in the worst case, this can lead to a fire in the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-UD30	「BMW 130i」	2007～2011	988
ABA-UF30		2005～2007	712
ABA-VB23	「BMW 323i」	2005～2007	9,877
ABA-VB25	「BMW 325i」	2005～2010	5,210
ABA-VB30	「BMW 330i」	2004～2006	1,141
ABA-VF25	「BMW 325Xi」	2007～2010	97
ABA-VD30	「BMW 330Xi」	2005～2007	139
ABA-VS25	「BMW 325i Touring」	2005～2010	2,124
ABA-NE25	「BMW 525i」	2005～2007	5,157
ABA-NU25		2007～2009	4,691
ABA-NE30	「BMW 530i」	2005～2007	2,100
ABA-NU30		2007～2009	1,605
ABA-NL25	「BMW 525i Touring」	2005～2007	1,285
ABA-PU25		2007～2010	1,531
ABA-NL30	「BMW 530i Touring」	2005～2007	470
ABA-PU30		2007～2010	386
ABA-PV30	「BMW 530Xi Touring」	2007～2009	98
ABA-EH30	「BMW 630i」	2005～2010	935
GH-EH30		2004～2005	77
ABA-VL25	「BMW X1 xDrive 25i」	2010～2011	1,381
ABA-PC25	「BMW X3 2.5Si」	2006～2010	3,621
ABA-PC30	「BMW X3 3.0Si」	2006～2010	639
ABA-FE30	「BMW X5 3.0si」	2007～2010	2,624
ABA-LM25	「BMW Z4 sDrive 23i」	2009～2011	2,895
ABA-BU25	「BMW Z4 2.5i」	2006～2008	1,700
ABA-BU30	「BMW Z4 3.0si」	2006～2008	450

ABA-DU30	「BMW Z4 Coupe 3.0si」	2006～2008	594
		Total	52,527

* This recall is newly notified to supplement the improvement measures for recalls Gai-2623 in 2018 and Gai-2869 in 2019.