

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3431	DATE	June 9. 2022
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In agricultural tractor, transmission device do not have bearing built into the HST due to improper manufacturing confirmation processes. Therefore, abnormal noise may be generated during traveling, the vehicle may not accelerate or decelerate smoothly, the gear may not stop even when the gear shift is stopped, or it may take time to switch even if the gear shift operation is performed in the forward / backward direction. If you continue to use it as it is, fail-safe will work and the engine may stop.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「JD-6130R」	2021	1	
		TOTAL	1	

