

Recall Notification Form

2nd June 2022

Dear Ministry of Land, Infrastructure, Transport and Tourism

Name of Reporter: BMW Japan Corp.

Name of CEO: Christian Wiedmann

Address: 1-9-1 Higashi Shinbashi, Minatoku, Tokyo

Recall Number	Gai-3401	Start of Recall	2nd June 2022
Structures, devices or devices that are recognized as non-conforming to the standards. And its causes.	The fuel tank assembly had defect at the upper part of it. The fuel pipe connector might have improperly connected. In occasion, if the connector disconnected due to vibrations, then fuel might leak, and engine will stop. In worst case, the car might have catch fire.		
Details of improvement measures	Check the fuel line. And if the pipe connector is not mounted correctly. Then fix it properly.		
Method to inform automobile users and automobile specific maintenance companies	Inform by calling or visiting.		

Car Name	Type Approval	Common Name	VIN of Recall vehicle and its production period.	Number of Recall Cars	Remark
Rolls-Royce	7BA-689X	Cullinan	SCATV4103NU210314~ SCATV4200NU210320 12th November 2021~ 19th November 2021	2	
	Total: 1 Type Approval	Total: 1 Valiant Car	(Range of whole Importing Period.) 12th November 2021~ 19th November 2021	Total 2	