

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3407	DATE	June 1, 2022
MANUFACTURE	Tesla, Inc. (Japanese Importer : Tesla Motors Japan G.K.)		
DESCRIPTION OF DEFECT	During fast-charging or preparation for fast-charging, the infotainment central processing unit ("CPU") may not cool sufficiently to prevent higher than expected temperatures, which may cause the CPU to slow processing or restart. Slower processing or restarted processing could cause the center screen display to lag or appear blank. A lagging or blank center screen display may cause drive modes (i.e., Drive, Neutral, or Reverse), and telltales to be unavailable, which may increase the risk of a collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-3L23P	Model 3	2022	5
ZAA-3L23PB		2022	40
ZAA-3L23T		2022	729
ZAA-3L13T		2022	641
ZAA-3L13T1		2021	5
		TOTAL	1,420