

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 3450	DATE	Jul. 22, 2022
MANUFACTURE	SCANIA CV AB (Japanese Importer: Bando motors Co. Ltd.)		
DESCRIPTION OF DEFECT	The plate inside the silencer on the compressor is not strong enough, therefore the intake air flow may cause the plate to vibrate and generate abnormal noise. In the worst case, the plate may break and it lead to damage the compressor and impossible to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2020	15
		TOTAL	15