

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3447	DATE	July 08, 2022
MANUFACTURE	Automobiles PEUGEOT Automobiles CITROEN DS Automobiles (Japanese Importer :Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, AC dryer receiver has insufficient capacity of accumulating water because its validation during development was not complete enough. As this consequence, motor coil of AC compressor becomes corroded in service and electrical insulation of the compressor decreases. In the worst case, warning message appears on dashboard and the vehicle can not move due to traction energy shut off by the safe mode.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-P21ZK01	「e-208」	2019-2022	596
ZAA-P24ZK01	「e-2008」	2019-2021	553
Unkown	「e-208」	2020	4
ZAA-C41ZK01	「e-C4」	2021-2022	76
ZAA-D34ZK01	「DS 3 CROSSBACK E-TENSE」	2019-2021	135
Unkown	「DS 3 CROSSBACK E-TENSE」	2020	1
		TOTAL	1,365