

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3445	DATE	July 4 th , 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>It cannot be ruled out that, due to long-term influences in areas with a high level of air humidity, moisture gets into the housing of the gas generator on the front-side front passenger airbag caused by possibility of an inflator manufacturing variability.</p> <p>In this case, if the front passenger airbag is activated, there may be an increased volume of internal pressure.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-AT18	「BMW 316ti」	2001～2004	19
GF-AL19	「BMW 318i」	1999～2000	4
	「BMW 318i Touring」	1999	1
GH-AL19	「BMW 318i」	2000～2001	37
	「BMW 318i Touring」	2000～2001	5
	「BMW 318Ci」	2000～2001	3
GH-AU20	「BMW 318ti」	2001～2003	31
GH-AY20	「BMW 318i」	2001～2004	36
	「BMW 318i Touring」	2001～2004	14
	「BMW 318Ci」	2004	1
GH-BX20	「BMW 318Ci」	2005	1
GF-AM20	「BMW 320i」	1999～2000	3
GH-AV22	「BMW 320i」	2000～2004	54
GF-AM25	「BMW 323i」	1999	2
GH-AV25	「BMW 325i」	2000～2003	15
	「BMW 325i Touring」	2000～2003	9
GF-AM28	「BMW 328i」	1999～2000	7
	「BMW 328Ci」	1999～2000	4
GH-AV30	「BMW 330i」	2000～2004	25
	「BMW 330Ci」	2000～2002	10
	「BMW 330Ci Cabriolet」	2000～2002	15
GH-BL32	「BMW M3」	2003	1
GH-M3CSL	「BMW M3 CSL」	2003	2
		Total	299