

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3446	DATE	July 4, 2022
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	It cannot be ruled out that, due to long-term influences in areas with a high level of air humidity, moisture gets into the housing of the gas generator on the front-side front passenger airbag caused by possibility of an inflator manufacturing variability. In this case, if the front passenger airbag is activated, there may be an increased volume of internal pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-3E46	ALPINA B3-3.3	2001-2002	3
GH-3E50	ALPINA B3S	2003-2004	2
		TOTAL	5