

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-3464	DATE	August 26th 2022
MANUFACTURE	Rolls-Royce Motor Cars Limited. (Japanese Importer : BMW Group Japan)		
DESCRIPTION OF DEFECT	<p>MLIT / BMW (Approved)</p> <p>Due to improper body domain controller (BDC) software, if the sidelights in the headlights fail, turn them off even though the sidelights in the front grille alone cannot meet the minimum luminous intensity. It does not meet the requirements of (Japanese) safety standards.</p> <p>The following contents are from RRMC Dealer Service Buiten</p> <p>A number of Rolls-Royce Ghost (RR21/22) vehicles fitted with the Grille Illumination feature (RSL option) have been identified as not meeting current regulations for specific markets. In the rare event that one of the headlight modules should fail, the Grille Illumination (which consists of a left and right lighting circuit) should also switch off on the same side as the failed headlight module. However, the current operation of this failure mode does not work as intended, resulting in the complete grille remaining illuminated, which does not align with current regulation. The Illuminated Grille failure mode logic has been updated with the vehicle software version RR21-22-03-550, which is included in ISTA 4.35.3x. Dealers should check for vehicles which are subject to this Technical Campaign using ISPA (Integrated Service Processes Application) or S-Gate/AIR</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-TV02 7BA-TV22	Rolls-Royce Ghost	2020-2022	164
		TOTAL	164