

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3465	DATE	28 September, 2022
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a software error in the instrument cluster, the brake booster malfunction is incorrectly indicated in the affected vehicles and therefore does not comply with Japanese safety compliance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-J1MB	Taycan 4S	2020-2022	330
ZAA-J1MC	Taycan Turbo		104
ZAA-J1MD	Taycan Turbo S		114
ZAA-J1NA1	Taycan		187
ZAA-J1NA1C	Taycan		275
ZAA-J1NA2	Taycan 4		66
ZAA-J1NB	Taycan 4S		99
ZAA-J1NC	Taycan Turbo		41
ZAA-J1ND	Taycan Turbo S		26
ZAA-J1NE	Taycan GTS		92
			Total