VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI 3472	DATE	Sep. 22, 2022	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer: SCANIA JAPANA Co. Ltd.)			
DESCRIPTION OF DEFECT	There have been instances of the turbocharger turbine wheel cracking due to improper manufacturing processes. It may occur damaging the turbocharger and oil carry on the turbine side down stream into the silencer, it lead to contaminate and damage the catalyst and DPF filter and exhaust gas purification function may not work properly. In the worst case, engine oil entering the silencer may cause a fire.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2019-2020	8
		TOTAL	8