

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3468	DATE	September 20, 2022
MANUFACTURE	Hyundai Motor Company (Japanese Importer : Hyundai Mobility Japan)		
DESCRIPTION OF DEFECT	Due to improper material of Hydrogen sensor, sensor may not detect a leak of Hydrogen. Driver can't recognized the leak of Hydrogen.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZBA-FE120	NEXO	2021	7
		TOTAL	7