

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	Gai-3485	DATE	October 27, 2022
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Due to inappropriate design of the clearance between impeller and the inlet cover of the in-tank fuel pump, fuel temperature rise may cause the impeller to interfere with the inlet cover. As a result, the fuel pump motor will malfunction. At the worst case, there will be a risk of stalling while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-BJAH5H	LUTECIA	2020	145
3BA-BJAH5H		2020	1,001
7BA-HJBH5H	CAPTUR	2020	249
3BA-HJBH5H		2020	240
		TOTAL	1,635