

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3495	DATE	October 27, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	Micro cracks at the flattening end of the anti-roll bar, may lead to increased material wear. This may result into a breaking of anti-roll bar at the area of the transition from the pipe geometry to the flattening ends geometry. A broken anti roll-bar leads to abnormal noises which are recognizable for the driver.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
AAA-F2DLZF	Audi A6 55Tq	2019	169
AAA-F2DLZS	Audi A7 SB 55Tq	2019	126
		Total	295