

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3479	Date	Oct. 25, 2022
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>Damaged front seatbelt pretensioner tube may have been installed on the seatbelt retractor. The damaged tube could prevent the pretensioner from correctly operating by not pre-tensioning the seatbelt in the event of an accident where it would normally operate. This may result in a reduced level or complete loss of pre-tensioning in the event of a crash and increased occupant injury.</p> <p>Inspect / Replace the seatbelt assemblies.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-DC2NC	F-PACE	2022	5
7BA -J60MD	F-TYPE	2022	1
3BA-LE62XAA	DEFENDER 90	2023	93
3BA-LE62XCA		2023	42
3BA-LE72XAA	DEFENDER 110	2023	51
3BA-LE72XCA		2022-2023	43
3BA-LW5SE	Range Rover Sport	2022	7
3BA-LY2XAC	Range Rover Velar	2022	21
3BA-LY2XCC		2022	4
3CA-LC2ND	Discovery Sport	2022	7
3CA-LE72WAB	DEFENDER 110	2022-2023	23
3CA-LE72WCB		2023	3
3CA-LR3WB	Discovery	2022-2023	3
3CA-LW3WHE	Range Rover Sport	2022	8
3CA-LY2NCC	Range Rover Velar	2022	1
3LA-LC15TD	Discovery Sport	2023	1
5BA-LC2XC		2022	12
5LA-LW2YC	Range Rover Sport	2022	2

7AA-LW3UD	Range Rover Sport	2022	3
		Total	330

(JIS A4 size)