

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI 3487	DATE	Oct. 20, 2022
MANUFACTURE	SCANIA CV AB (Japanese Importer: Putzmeister Japan CO.LTD. )		
DESCRIPTION OF DEFECT	<p>There have been instances of slots missing at the end of track rod. Therefore, even if the end of the track rod is tightened with a clamp, the ball joint may not be secured enough.</p> <p>In the worst case, the ball joint got loose from the track rod when maneuvering which may result in loss of steering control.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	BSF38-5.16H concrete pump LPGRS series Truck	2021	2
		TOTAL	2