

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.		DATE	
MANUFACTURE	Bombardier Recreational Products Inc. Japanese Importer : BRP Japan		
DESCRIPTION OF DEFECT	The handlebar stem bolt may break suddenly. This could lead to a loss of steering control and increase the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2FF	Can-Am RYKER600	17 Nov 2021 to 5 Jul 2022	134
2FG	Can-Am RYKER900		
2HH	Can-Am RYKER RALLY		
2JG	Can-Am RYKER SPORT		
		TOTAL	134