

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / **Import Vehicles**

CAMPAIGN No.	GAI 3522	DATE	Nov. 29.2022
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The clutch cover screws may loosen, due to a faulty anti-friction coating on the screw threads. This may lead to a loss of preload in the screw connection; consequently, oil may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-S10AA	「BMW S1000R」	2022	17
	「BMW S1000XR」		9
	「BMW S1000RR」		43
	「BMW M1000RR」		27
		TOTAL	96