

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3493	DATE	22.11.2022
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	<p>The anomaly occurs in the engine control unit (ECU). The threshold value of the temperature sensor monitoring the temperature of the exhaust pipe has been incorrectly set at 200°C. If this threshold is passed, the check engine light will illuminate and the engine performances will be decreased. In addition, after the car stops, the engine will turn off within 90 sec. if the car continues to stay in idle. In this case, the engine may not be restarted and the vehicle may not be able to drive with the electric motor.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7LA-173H	SF90Stradale,SF90Spider	2020-2021	135
		TOTAL	135