

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3515	DATE	Novemenber 22, 2022
MANUFACTURE	Automobiles PEUGEOT DS Automobiles (Japanese Importer :Stellantis Japan Ltd. )		
DESCRIPTION OF DEFECT	On affected vehicles, due to improver software of engine control unit and improper tightening torque of rear driveshaft nut, excessive stress bigger than presumed during development may be produced on rear driveshafts under specific driving condition. As this consequence, rear driveshafts may break and cause waraning light illumination and noise.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3LA-P845G06H	「3008 HYBRID4」	2020-2021	334
3LA-X745G06H	「DS 7 CROSSBACK E-TENSE」	2020-2021	84
		TOTAL	418