

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3509	Date	November 2, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	<p>On Golf vehicles of a limited production period, the radiator may not be properly fastened in production. An incorrectly performed fastening of the radiator can come loose and tilt backwards, which can lead to contact and damage to the coolant hose and poly V-belt. This can result in coolant loss. The coolant loss is shown via the warning lamp in the instrument cluster. In the worst case, the vehicle cannot be driven due to coolant leakage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-CDDNP	Golf GTI 2.0/180kW	MY2022-2023	1,260
		Total	1,260