

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3510	Date	November 2, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	The washing performance of the headlight washer system is insufficient due to improper onboard supply control program.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1TCZD	Golf Touran 1.4/110kW	MY2018-2020	1,744
LDA-1TDFG	Golf Touran TDI/110kW	MY2018-2020	304
3BA-1TDPC	Golf Touran 1.5/110kW	MY2021-2022	15
3DA-1TDFG	Golf Touran TDI/110kW	MY2022	1
		Total	2,064