

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3511	Date	November 2, 2022
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the seat belt tensioner with force limiter on the three-point automatic seat belts of the front seats have insufficient assembly force for component parts due to inappropriate manufacturing control. In the event of a front crash and triggering of the airbag, there is a possibility that the seat belt will not have enough retention force. In the worst case, this insufficient retention force can lead to injuries.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-CDDLA	Golf 1.0/81kW	2021-2022	2,401
3AA-CDDLAV	Golf Variant 1.0/81kW	2021-2022	388
3AA-CDDFY	Golf 1.5/110kW	2021-2022	2,856
3AA-CDDFYV	Golf Variant 1.5/110kW	2021-2022	660
3BA-CDDNP	Golf GTI 2.0/180kW	2022	198
3DA-CDDTS	Golf TDI/110kW	2021-2022	239
		Total	6,742