

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	Gai-3497	DATE	2022/11/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain C-Class Sedan (206 platform) vehicles, moisture might enter into the signal acquisition and actuation module in case of a water ingress into the trunk.</p> <p>In this case, a short circuit might occur in the signal acquisition and actuation module (SAM).</p> <p>In this connection, a risk of fire cannot be excluded completely.</p> <p>Additionally, a short circuit might lead to various malfunctions. Among others, the exterior lighting on the rear of the vehicle might fail, the rear seat backrests might fold unintentionally and the rear view camera might not be available.</p> <p>Thus, the risk of a crash or injury would be increased and local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-206041C	C180	2022	536
5AA-206042C	C200		3,249
5AA-206043C	C200 4MATIC		492
3CA-206004C	C220d		2,409
		TOTAL	6,686