

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3501	DATE	2022/11/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain CLA (118 platform), A-Class (177 platform) and B-Class (247 platform) vehicles the mounting of the transmission bearing cover might not meet specifications. In this case, the transmission bearing cover might detach from the mounting. Subsequently, an oil leakage might occur. Due to the position and amount of the potential oil leakage, a possible risk of fire or danger for the following traffic can be ruled out. Furthermore, if the oil level falls below a certain level, a warning would be displayed in the instrument cluster. However, local legal requirements might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-177012	A200d	2021	72
3DA-177112	A200d Sedan		9
3DA-247012	B200d		39
3DA-118312M	CLA200d	2022	1
3DA-118612M	CLA200d Shooting Brake	2021	119
		TOTAL	357