

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3537	DATE	2022/12/13
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain GLB (247 platform) vehicles the ESP unit might be mechanically damaged. In this case, moisture might ingress into the ESP control unit and internal components of the ESP unit might be affected from damages. As a consequence, ESP functions (e.g. vehicle stability control, ABS) might be deactivated and a risk of fire due to an internal short circuit cannot be ruled out. This would increase the risk of a crash or injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-247612M	GLB200d	2021	14
		TOTAL	14