

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3540	DATE	2022/12/13
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain S-Class (223 platform) vehicles the safety seal on the electrical plug connector of the steering column module might not have been installed correctly.</p> <p>In this case, the plug connector of the steering column module might become loose due to vibrations during driving. Subsequently, different functions (e.g. ESP, driver airbag, turn indicator) might not be available and a gear change might no longer be possible. This would increase the risk of crash and injury, respectively.</p> <p>Furthermore, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-223133	S400d 4MATIC	2021	1
5AA-223163	S500 4MATIC		1
5AA-223163			1
		TOTAL	3