

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|--|------|--------------|
| CAMPAIGN No. | Gai-3513 | DATE | Dec. 9, 2022 |
| MANUFACTURE | Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.) | | |
| DESCRIPTION OF DEFECT | The handlebar (P/N 55801154) on certain Model Year 2022 RH975 Nightster motorcycles, built between 08/24/21 and 09/09/22, may not have been welded properly between the inner and outer sections and may break. A broken handlebar could lead to a loss of steering control and an increased risk of a crash if this occurs while riding.. | | |
| | | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| 8BL-RH1 | Nightster | 2022 | 773 |
| | | TOTAL | 773 |